



## **Technical Bulletin – TBN-008**

**Product:** LCV1 Toyota Landcruiser 78/79 series.

**Subject:** Spring Cover Plugs – Thread Changes Referenced to Serial Number

### **Summary:**

LCV1 rear brakes produced before 01/12/04 used M16 x 1.5 Taper Spring Cover Plugs, part number 15-2520.

LCV1 rear brakes produced after 01/12/04 used 3/8 BSPT Spring Cover Plugs, part number 70-3006.

### **Description:**

In December of 2004, the spring cover plugs and the thread tapped into the spring cover (part number 15-2781) were changed from M16 x 1.5 taper to 3/8 BSPT. Brakes produced before 1/12/04 use part number 15-2520. Brakes produced after 1/12/04, or those fitted with new spring covers after this date use part number 70-3006.

**Prepared by:** Jasper Stewart  
**Issue Date:** 05/07/2005  
**Issue Revision:** 1

Safe Effect Pty. Ltd.  
Unit 3/75 Erindale Rd  
Balcatta WA 6021  
AUSTRALIA  
PO Box 632  
Balcatta WA 6914

Tel: +61(08) 9240 2713  
Fax: +61 (08) 9240 1577  
Email: [info.perth@safeffect.com](mailto:info.perth@safeffect.com)  
Web: [www.safeffect.com](http://www.safeffect.com)